



Notification of Hazardous Waste Site

TXS-000-001-109 000458

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

RECEIVED

JUN 10 1981

6AEP

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name MAGNA CORPORATION
Street P. O. BOX 33387
City HOUSTON State TEXAS Zip Code 77033

B Site Location: TXD 00 080 7875

Enter the common name (if known) and actual location of the site.

Name of Site MAGNA CORPORATION (HOUSTON)
Street 2434 HOLMES ROAD
City HOUSTON County HARRIS State TEXAS Zip Code 77051

EPA-ID-TXD 000807875

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) McDONALD, G.C. - REGULATORY AFFAIRS MANAGER
Phone (713) 791-6389 /or CARLOS A. STENNETT (713) 791-6343
ENVIRONMENTAL REGULATIONS SPECIALIST

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 7-12-80 To (Year) 8-26-80

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☒ Organics
- 2. ☒ Inorganics
- 3. ☒ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☒ Acids
- 7. ☒ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☒ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

SUPERFUND FILE

FEB 12 1993

REORGANIZED

Notification of Hazardous Waste

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☒ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 117,936 or (4,368Y³)

gallons _____

Total Facility Area

square feet _____

acres 19.35 Acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

(SEE ATTACHMENT A)

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

(SEE ATTACHMENT B)

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name MAGNA CORPORATION

Street 2434 HOLMES ROAD

City HOUSTON

State TX. Zip Code 77051

Signature


A. C. McDonald

Date 7/4/81

G. C. McDonald - Regulatory Affairs Manager

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

ATTACHMENT A



ATTACHMENT B

ITEM I - DESCRIPTION OF SITE:

On a routine inspection of the facility described on this form on July 12, 1980, facility personnel discovered an area in the rear of the facility where the soil was contaminated with waste chemicals. Additional detailed site inspection and exploratory excavation work at this site indicated the need for immediate excavation and removal of this soil.

A notification was made to TECO and the Texas Department of Water Resources (TDWR) Division of Solid Waste Management in Austin, and Mr. Clarence Johnson, a field representative of the TDWR Deer Park Office, was assigned to work with Magna Corporation on this problem.

The waste originated from waste chemicals, from production batches (TDWR - Class Code 150570) excavation at the site unearthed drums with the chemical contained soil. Samples were taken of two (2) drums to determine content of these. In addition, peripheral trenches were dug to determine if any ground water and/or chemical migration problems existed.

CORRECTIVE ACTION:

1. After exploratory work at the site, a refilled effort was made to prevent undue run-off until a full excavation could be initiated.
2. In consultation with TDWR, efforts were initiated to locate potential waste disposal sites, and certified waste disposers for hauling and disposal.
3. Successful identification of a waste disposal site and a carrier, started the removal of 1,000 y³ of contaminated soil. During this time, TDWR representative and Magna personnel split water samples to determine extent (if any) of water contamination.
4. TDWR representative advised that the excavation should be sealed with four (4) feet of clay prior to filling with dirt. Magna Corporation implemented this recommended TDWR - Closure procedure.

Full documentation of all correspondence and activities associated with this site are on file.